Date: October 10, 2016

Lamarco M. Morrison, MSCM Greenville Recreation and Parks Dept. City of Greenville, NC (252) 329-4242



Tower Engineering Professionals 326 Tryon Road Raleigh, NC 27603 (919) 661-6351 <u>kedwards@tepgroup.net</u>

Subject: Maintenance and Condition Assessment Report

| Tower Designation: | Site Number: Site Name: | Unknown Greenville Town Commons |
|-------------------------------|---|------------------------------------|
| Engineering Firm Designation: | TEP Project Number: | 73500_98734 |
| Site Data: | 105 East 1st Street, Greenville, F Lat., Long.: 35.615773, -77.3691 (N 35° 36' 56.78″, W 77° 22' 8.76 185-ft ± – Guyed Tower | Pitt County, NC 27858 00 5") |

Dear Mr. Morrison,

Tower Engineering Professionals (TEP) completed a periodic inspection for the above referenced site. The onsite investigation was performed by Kyle Edwards, P.E., C.W.I. and Cameron Torgent, E.I. of TEP during the September 23, 2016 site visit. The inspection was in accordance with the ANSI/TIA-222-G-2005, Annex J: Maintenance and Condition Assessment (Normative), including all addendums (addendums TIA-222-G-1 2007 and TIA 222-G-2 2009); the checklist can be found on pages 3 thru 8 of this report.

Observations and recommendations are listed herein. For the purpose of this inspection, the tower legs were named by letter according to the magnetic azimuth defined by a line from the center of tower to the leg. "A" leg is the leg closest to magnetic north, followed clockwise by "B" and "C." Guy levels were numbered from the ground up. Guy levels 1-4 are at the 39.5-ft, 79.5-ft, 119.5-ft, and 159.5-ft elevations respectively.

Thank you for the opportunity to provide this service for you. If you have any questions or comments, please contact our office.

Respectfully submitted by:

Haldane, P.E., G.C., C.W.I.



TABLE OF CONTENTS

1) ANSI/TIA-222-G-MAINTENANCE AND CONDITION ASSESSMENT

2) SUMMARY

- 3) APPENDIX A Guy Tensions
- 4) APPENDIX B

Tower Plumb and Twist Measurements

5) APPENDIX C

Typical Guy Anchor Configuration



ANSI/TIA-222-G MAINTENANCE AND CONDITION ASSESSMENT

A. STRUCTURE CONDITION

| A.1. Damaged members (legs and bracing) | | | | |
|---|--|---|----------------|--|
| Okay | Possible Improvement | Needs Repair | Not Applicable | |
| Notes: Bent diagonal observed o | n the CA-face at 163-ft. See summ | ary for details. | | |
| A.2. Loose members | | | | |
| Okay | Possible Improvement | Needs Repair | Not Applicable | |
| Notes: | | | | |
| A.3. Missing members | | | | |
| Okay | Possible Improvement | Needs Repair | Not Applicable | |
| Notes: | | | | |
| A.4. Climbing facilities, platforms, catwalks – all secure | | | | |
| A.4. Climbing facilities, platform | s, catwalks – all secure | | | |
| A.4. Climbing facilities, platform | s, catwalks – all secure | Needs Repair | Not Applicable | |
| A.4. Climbing facilities, platform: Okay Notes: No safety climb cable is in | s, catwalks – all secure Possible Improvement stalled on tower. See summary for | Needs Repair | Not Applicable | |
| A.4. Climbing facilities, platform: Okay Notes: No safety climb cable is in A.5. Loose and/or missing bolts a | s, catwalks – all secure Possible Improvement stalled on tower. See summary for and/or nut locking devices | Needs Repair details. | Not Applicable | |
| A.4. Climbing facilities, platform: Okay Notes: No safety climb cable is in A.5. Loose and/or missing bolts a Okay | s, catwalks – all secure Possible Improvement stalled on tower. See summary for and/or nut locking devices Possible Improvement | Veeds Repair details. | Not Applicable | |
| A.4. Climbing facilities, platform: Okay Notes: No safety climb cable is in A.5. Loose and/or missing bolts a Okay Notes: Guy anchor C has an under | s, catwalks – all secure Possible Improvement stalled on tower. See summary for and/or nut locking devices Possible Improvement ersized connection bolt. See summ | Veeds Repair details. | Not Applicable | |
| A.4. Climbing facilities, platform: Okay Notes: No safety climb cable is in A.5. Loose and/or missing bolts a Okay Notes: Guy anchor C has an under A.6. Visible cracks in welded con | s, catwalks – all secure Possible Improvement stalled on tower. See summary for and/or nut locking devices Possible Improvement ersized connection bolt. See summ nections | Needs Repair details. Needs Repair Image: A start of the start of t | Not Applicable | |
| A.4. Climbing facilities, platform: Okay Notes: No safety climb cable is in A.5. Loose and/or missing bolts a Okay Notes: Guy anchor C has an under A.6. Visible cracks in welded com Okay | s, catwalks – all secure Possible Improvement stalled on tower. See summary for and/or nut locking devices Possible Improvement ersized connection bolt. See summ nections Possible Improvement | Needs Repair details. Needs Repair ary for details. Needs Repair | Not Applicable | |

B. FINISH

| B.1. Paint and/or galvanizing condition | | | | |
|---|-------------------------------------|-------------------------------------|-------------------------|--|
| Okay | Possible Improvement | 🔀 Needs Repair | Not Applicable | |
| Notes: Most of the tower's paint | has flaked off. See summary for det | ails. | | |
| B.2. Rust and/or corrosion condit | ion including mounts and accessor | ies | | |
| Okay | Possible Improvement | 🔀 Needs Repair | Not Applicable | |
| Notes: Significant corrosion on al | tower members, guy wires, guy an | chors, bolts, and appurtenances. Se | ee summary for details. | |
| B.3. FAA or ICAO color marking co | onditions | | | |
| Okay | Possible Improvement | Needs Repair | Not Applicable | |
| Notes: | | | | |
| B.4. Water collection in members (to be remedied, e.g., unplug drain holes, etc.) | | | | |
| Okay | Possible Improvement | Needs Repair | Not Applicable | |
| Notes: | | | | |





C. LIGHTING

| C.1. Conduit, junction boxes, and fasteners (weather tight and secure) | | | | |
|--|--|----------------------------------|----------------|--|
| Okay | Possible Improvement | Needs Repair | Not Applicable | |
| Notes: Significant corrosion obser | rved on lighting conduit from 0-ft to | 185-ft. See summary for details. | | |
| C.2. Drains and vents openings (ι | unobstructed) | | | |
| Okay | Possible Improvement | Needs Repair | Not Applicable | |
| Notes: | | | | |
| C.3. Wiring Condition | | | | |
| Okay | Possible Improvement | Needs Repair | Not Applicable | |
| Notes: | | | | |
| C.4. Light Lenses | | | | |
| Okay | Possible Improvement | Needs Repair | Not Applicable | |
| Notes: Sidelight latches appear to | be damaged. See summary for det | ails. | | |
| C.5. Bulb condition | | | | |
| Okay | Possible Improvement | Needs Repair | Not Applicable | |
| Notes: Sidelights were not operat | ional at the time of inspection. See | summary for details. | | |
| C.6.a. Controllers functioning (Fla | asher) | | | |
| Okay | Possible Improvement | Needs Repair | Not Applicable | |
| Notes: | | | | |
| C.6.b. Controllers functioning (Pr | C.6.b. Controllers functioning (Photo control) | | | |
| Okay | Possible Improvement | Needs Repair | Not Applicable | |
| Notes: | | | | |
| C.6.c. Controllers functioning (Ala | arms) | | | |
| Okay | Possible Improvement | Needs Repair | Not Applicable | |
| Notes: | | | | |

D. GROUNDING

| D.1. Connections | | | | |
|--|----------------------|--------------|----------------|--|
| Okay | Possible Improvement | Needs Repair | Not Applicable | |
| Notes: | | | | |
| D.2. Corrosion | | | | |
| 🔀 Okay | Possible Improvement | Needs Repair | Not Applicable | |
| Notes: | | | | |
| D.3. Lightning protection (secured to structure) | | | | |
| 🔀 Okay | Possible Improvement | Needs Repair | Not Applicable | |
| Notes: | | | | |





E. ANTENNAS AND LINES

| E.1. Antenna condition | | | |
|------------------------------------|-------------------------------------|--------------|----------------|
| 🔀 Okay | Possible Improvement | Needs Repair | Not Applicable |
| Notes: | | | |
| E.2. Mount and/or ice shield con | dition (bent, loose, and/or missing | members) | |
| 🔀 Okay | Possible Improvement | Needs Repair | Not Applicable |
| Notes: | | | |
| E.3. Feed line condition (flanges, | seals, dents, jacket damage, groun | ding, etc.) | |
| 🔀 Okay | Possible Improvement | Needs Repair | Not Applicable |
| Notes: | | | |
| E.4. Hanger condition (snap-ins, b | oolt on, kellum grips, etc.) | | |
| Okay | Possible Improvement | Needs Repair | Not Applicable |
| Notes: | | | |
| E.5. Secured to structure | | | |
| 🗙 Okay | Possible Improvement | Needs Repair | Not Applicable |
| Notes: | | | |

F. OTHER APPURTENANCES (WALKWAYS, PLATFORMS, SENSORS, FLOODLIGHTS, ETC.)

| F.1. Condition | | | |
|---------------------------|----------------------|--------------|----------------|
| Okay | Possible Improvement | Needs Repair | Not Applicable |
| Notes: | | | |
| | | | |
| F.2. Secured to structure | | | |
| F.2. Secured to structure | Possible Improvement | Needs Repair | Not Applicable |

G. INSULATOR CONDITION

| G.1. Cracking and chipping | | | |
|-----------------------------------|----------------------|--------------|----------------|
| Okay | Possible Improvement | Needs Repair | Not Applicable |
| Notes: | | | |
| G.2. Cleanliness of insulators | | | |
| Okay | Possible Improvement | Needs Repair | Not Applicable |
| Notes: | | | |
| G.3. Spark gaps set properly | | | |
| Okay | Possible Improvement | Needs Repair | Not Applicable |
| Notes: Tower is grounded out per | site tech. | | |
| G.4. Isolation transformer condit | ion | | |
| Okay | Possible Improvement | Needs Repair | Not Applicable |
| Notes: | | | |
| G.5. Bolts and connection secure | | | |
| Okay | Possible Improvement | Needs Repair | Not Applicable |
| Notes: | | | |





H. GUYS

| H.1. Strand condition (corrosion | , breaks, nicks, kinks, etc.) | | |
|-----------------------------------|--|--------------------------------------|---------------------------|
| Okay | Possible Improvement | Needs Repair | Not Applicable |
| Notes: Significant corrosion on a | ll tower members, guy wires, guy a | nchors, bolts, and appurtenances. | See summary for details. |
| H.2.a. Guy Hardware Conditions | (Turnbuckles or equivalent (secur | e and safety properly applied) | |
| Okay | Possible Improvement | Needs Repair | Not Applicable |
| Notes: | | | |
| H.2.b. Guy Hardware Conditions | (Cable thimbles properly in place | (if required)) | |
| Okay | Possible Improvement | Needs Repair | Not Applicable |
| Notes: No guy wire cable thimbl | es installed at terminations. | | |
| H.2.c. Guy Hardware Conditions | (Service sleeves properly in place | (if required)) | |
| Okay | Possible Improvement | Needs Repair | Not Applicable |
| Notes: | | | |
| H.2.d.i. Guy Hardware Condition | s (Cable connectors (end fittings) | Cable clamps applied properly and | bolts tight)) |
| Okay | Possible Improvement | Needs Repair | Not Applicable |
| Notes: All Crosby clamps are corr | roded. See summary for details. | | |
| H.2.d.ii. Guy Hardware Conditio | ns (Cable connectors (end fittings) | (Wire serving properly applied)) | |
| Okay | Possible Improvement | Needs Repair | Not Applicable |
| Notes: | | | |
| H.2.d.iii. Guy Hardware Condition | ns (Cable connectors (end fittings) | (No signs of slippage or damaged | strands)) |
| Okay | Possible Improvement | Needs Repair | Not Applicable |
| Notes: | | | |
| H.2.d.iv. Guy Hardware Condition | ns (Cable connectors (Preformed v | wraps – properly applied, fully wra | pped, & sleeve in place)) |
| Okay | Possible Improvement | Needs Repair | Not Applicable |
| Notes: | | | |
| H.2.d.v. Guy Hardware Conditio | ns (Cable connectors (<i>end fittings</i>) | (Poured sockets secure and showi | ng no separation)) |
| Okay | Possible Improvement | Needs Repair | Not Applicable |
| Notes: | | | |
| H.2.d.vi. Guy Hardware Condition | ns (Cable connectors (Shackles, bo | lts, pins, and cotter pins secure an | d in good condition)) |
| Okay | Possible Improvement | Needs Repair | Not Applicable |
| Notes: Surface corrosion observ | ed on all guy wire shackles. See sun | nmary for details. | |
| H.3. Guy tensions | | | - |
| Okay | Possible Improvement | Needs Repair | Not Applicable |
| Notes: Guy tensions not within t | he ANSI/TIA-222-G-2005 recomme | nded limits. See Appendix A for det | tails. |
| H.4. Measure guy tensions | | | |
| Okay | Possible Improvement | Needs Repair | Not Applicable |
| Notes: Tensions measured using | a Dillon tension meter. | | |
| H.5. Record temperature, wind | speed and wind direction | 1 | |
| Okay | Possible Improvement | Needs Repair | Not Applicable |
| Notes: Temperature was 73 deg | rees Fahrenheit at the time of meas | surement. Wind was calm at the tin | ne of inspection. |



I. CONCRETE FOUNDATIONS

| I.1.a. Ground condition (Settlement, movement or earth cracks) | | | |
|--|-------------------------------------|---------------|----------------|
| Okay | Possible Improvement | Needs Repair | Not Applicable |
| Notes: | | | |
| I.1.b. Ground condition (Erosion) | | | |
| Okay | Possible Improvement | Needs Repair | Not Applicable |
| Notes: | | | |
| I.1.c. Ground condition (Site con | dition (standing water, drainage, t | trees, etc.)) | |
| Okay | Possible Improvement | Needs Repair | Not Applicable |
| Notes: Standing water was obser | rved at A and B guy anchors. | | |
| I.2.a. Anchorage condition (Nuts | and/or nut locking device (tighter | ned)) | |
| Okay | Possible Improvement | Needs Repair | Not Applicable |
| Notes: | | | |
| I.2.b. Anchorage condition (Grou | it condition) | | |
| Okay | Possible Improvement | Needs Repair | Not Applicable |
| Notes: | | | |
| I.2.c. Anchorage condition (Anch | orages and/or anchor rod condition | on) | |
| Okay | Possible Improvement | Needs Repair | Not Applicable |
| Notes: | | | |
| I.3.a. Concrete condition (Cracking | ng, spalling, or splitting) | | |
| Okay | Possible Improvement | Needs Repair | Not Applicable |
| Notes: | | | |
| I.3.b. Concrete condition (Chippe | ed or broken concrete) | | |
| Okay | Possible Improvement | Needs Repair | Not Applicable |
| Notes: | | | |
| I.3.c. Concrete condition (Honeycombing) | | | |
| Okay | Possible Improvement | Needs Repair | Not Applicable |
| Notes: | | | |
| I.3.d. Concrete condition (Low sp | oots to collect moisture) | | |
| Okay | Possible Improvement | Needs Repair | Not Applicable |
| Notes: | | | - |





J. GUYED MAST ANCHORS

| J.1. Settlement, movement or earth cracks | | | | |
|--|-------------------------------------|-----------------------------------|----------------|--|
| Okay | Possible Improvement | Needs Repair | Not Applicable | |
| Notes: | | | | |
| J.2. Backfill heaped over concrete | e for water shedding | | | |
| Okay | Possible Improvement | Needs Repair | Not Applicable | |
| Notes: | | | | |
| J.3. Anchor rod condition below e | earth (Maintain required structural | capacity of anchor during explora | tion.) | |
| Okay | Possible Improvement | 🔀 Needs Repair | Not Applicable | |
| Notes: Significant corrosion obser | ved on all guy anchor rods above g | rade. See summary for details. | | |
| J.4. Corrosion control measures (| galvanizing, coating, concrete enca | sement, cathodic protection syste | ms, etc.) | |
| Okay | Possible Improvement | 🔀 Needs Repair | Not Applicable | |
| Notes: Guy anchors have no corrosion control measures installed. | | | | |
| J.5. Anchor heads clear of earth | | | | |
| Okay | Possible Improvement | Needs Repair | Not Applicable | |
| Notes: | | | | |

K. TOWER ALIGNMENT

| K.1. Tower Plumb and Twist | | | | |
|---|----------------------|----------------|----------------|--|
| Okay | Possible Improvement | 🔀 Needs Repair | Not Applicable | |
| Notes: Tower twist and plumb not within ANSI/TIA-222-G-2005 recommended limits. See Appendix B for details. | | | | |





| Photograph | Observations and Recommendations |
|------------|---|
| | A.1. Damaged members (legs and bracing) Observation: Bent diagonal observed on the CA-face at 163-ft. |
| | Recommendation: Repair, modify, or replace damaged member. |
| | A.4. Climbing facilities, platforms, catwalks – all secure |
| | Observation: No safety climb cable is installed on the tower. Recommendation: Install safety climb cable per the requirements of ANSI/TIA- 222-G. |
| | A.5. Climbing facilities, platforms, catwalks – all secure |
| | Observation: Guy anchor C has an undersized connection bolt. |
| | Recommendation: |
| | Install a properly sized connection bolt per the tower manufacturer drawings. Install nut locking devices on all |
| | new bolts. Tighten all nuts per the AISC "turn of the nut" method. Install nut locking devices on all new bolts. |





| Photograph | Observations and Recommendations |
|------------|---|
| | C.1. Conduit, junction boxes, and fasteners (weather tight and secure) Observation: Significant corrosion observed on lighting conduit from 0-ft to 185-ft. Recommendation: Replace lighting conduit. |
| | C.4. Light Lenses Observation: Sidelight latches appear to be damaged. Recommendation: Repair or replace sidelight latches. |
| | C.5. Bulb condition Observation: Sidelights were not operational at the time of inspection. Recommendation: Repair or replace sidelights. |





| Photograph | Observations and Recommendations |
|------------|--|
| | <u>B.1. Paint and/or galvanizing condition</u> Observation: Most of the tower's paint has flaked off. Recommendation: |
| | Repaint structure after the corrosion control measures recommended in Section B.2 have been completed. |
| | |
| | |





| Photograph | Observations and Recommendations |
|------------|--|
| | B.2. Rust and/or corrosion condition including mounts and <u>accessories</u> |
| | Observation: Significant corrosion observed on all tower members, guy wires, guy anchors, bolts, and appurtenances. |
| | Recommendation: Clean areas of corrosion down to sound metal and coat with two brush coats of ZRC cold galvanizing compound or approved equivalent. If area loss greater than 10% of member thickness is observed while cleaning steel, member must be replaced. |
| | Replace all corroded bolts. Install nut locking devices on all new bolts. Tighten all nuts per the AISC "turn of the nut" method. Install nut locking devices on all new bolts. |
| | Replace all corroded guy wire hardware. |
| | |
| | |
| | |
| | |





| Photograph | Observations and Recommendations |
|------------|--|
| | H.2.d.i. Guy Hardware Conditions (Cable connectors (end fittings) (Cable clamps applied properly and bolts tight)) Observation: All guy wire Crosby clamps are corroded Recommendation: Remove and re-install at least (2) Crosby clamps at each guy wire termination. Install Crosby clamps per the manufacturer specifications. |
| | H.2.d.vi. Guy Hardware Conditions (Cable connectors (Shackles, bolts, pins, and cotter pins secure and in good condition)) Observation: Surface corrosion observed on all guy wire shackles. Recommendation: Replace all guy wire shackles. |





| Photograph | Observations and Recommendations |
|------------|---|
| | J.3. Anchor rod condition below earth (Maintain required structural capacity of anchor during exploration.) Observation: Significant corrosion observed on all guy anchor rods above grade. Anchor rods could not be inspected below grade due to standing water. |
| | Recommendation: A guy anchor investigation below grade must be performed to determine the extent of corrosion damage. |







| Photograph | Observations and Recommendations |
|------------|---|
| | K.1. Tower Plumb and Twist Observation: Tower twist and plumb not within ANSI/TIA-222-G-2005 recommended limits. See Appendix B for details. Recommendation: Ensure that tower is within plumb tolerance while retensioning guy wires. |





APPENDIX A: GUY TENSIONS

| Guy Path | Guy # | Guy Size (diameter in inches) Measured | -10% of Initial Tension at 60°F (lbs) | +10% of Initial Tension at 60°F (lbs) | Measured tension converted to 60°F (lbs) | Results |
|-------------|-------------|---|---|---|---|---------|
| | 1 at 39.5' | 1/4 | 598.5 | 731.5 | 891 | HIGH |
| • | 2 at 79.5' | 1/4 | 598.5 | 731.5 | 933 | HIGH |
| A | 3 at 119.5' | 1/4 | 598.5 | 731.5 | 707 | ОК |
| | 4 at 159.5' | 1/4 | 598.5 | 731.5 | 482 | LOW |
| | | | | | | |
| | 1 at 39.5' | 1/4 | 598.5 | 731.5 | 802 | HIGH |
| Р | 2 at 79.5' | 1/4 | 598.5 | 731.5 | 948 | HIGH |
| Б | 3 at 119.5' | 1/4 | 598.5 | 731.5 | 635 | ОК |
| | 4 at 159.5' | 1/4 | 598.5 | 731.5 | 483 | LOW |
| | | | | | | |
| | 1 at 39.5' | 1/4 | 598.5 | 731.5 | 757 | HIGH |
| <u> </u> | 2 at 79.5' | 1/4 | 598.5 | 731.5 | 1038 | HIGH |
| С | 3 at 119.5' | 1/4 | 598.5 | 731.5 | 560 | LOW |
| | 4 at 159.5' | 1/4 | 598.5 | 731.5 | 585 | LOW |

Table A-1 (Assumed Initial Tension is 10% of Breaking Strength)





APPENDIX B: TOWER PLUMB AND TWIST MEASUREMENTS

| | Reference Elevation (above conc.) | Twist with Respect To Base (°) | Allowable Twist with Respect To Base (°) | Relative Twist Between Reference Elevations (°) | Allowable Twist Between Reference Elevations (°) |
|-------|---|--------------------------------------|--|---|--|
| S | 159.5-ft | 6.97 | ± 5.00 | | |
| lent | | | | 1.40 | ± 2.00 |
| ren | 119.5-ft | 5.57 | ± 5.00 | | |
| asu | | | | 1.40 | ± 2.00 |
| Me | 79.5-ft | 4.17 | ± 3.98 | | |
| vist | | | | 1.39 | ± 2.00 |
| εr Τν | 39.5-ft | 2.78 | ± 1.98 | | |
| OWE | | | | 2.78 | ± 1.98 |
| Ĕ | 0.0-ft | 0.00 | ± 0.00 | | |

Table B-1: Tower Twist Measurements





| | Reference Elevation (above conc.) | Resultant Deflection (in) | Allowable Resultant Deflection (in) per TIA | Relative Deflection Between Reference Elevations (in) | Allowable Deflection Between Reference Elevations (in) per TIA |
|-------------|---|------------------------------|--|---|--|
| | 159.5-ft | +1.02 | ± 4.79 | | |
| | | | | +0.235 | ± 1.2 |
| ion its | 119.5-ft | +1.22 | ± 3.59 | | |
| hen | | | | +0.235 | ± 1.2 |
| Def urer | 79.5-ft | +1.02 | ± 2.39 | | |
| ver easi | | | | +0.235 | ± 1.2 |
| ΣQ | 39.5-ft | +0.81 | ± 1.19 | | |
| | | | | +0.813 | ± 1.2 |
| | 0.0-ft | 0.00 | ± 0.00 | | |

Table B-2: Lateral Deflection Measurements





APPENDIX C: TYPICAL GUY ANCHOR CONFIGURATION



